
3.3.2 Orienting and securing the robot Continued

	Action	Note
9	Tighten the bolts in a crosswise pattern to ensure that the base is not distorted.	Tightening torque: 20 Nm±2 Nm

Hole configuration, base

This illustration shows the hole configuration used when securing the robot.



xx2200000191